

**THIS PAGE IS INSERTED BY OIPE SCANNING
AND IS NOT PART OF THE OFFICIAL RECORD**

Best Available Images

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

BLACK BORDERS

TEXT CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT

BLURRY OR ILLEGIBLE TEXT

SKEWED/SLANTED IMAGES

COLORED PHOTOS HAVE BEEN RENDERED INTO BLACK AND WHITE

✓ VERY DARK BLACK AND WHITE PHOTOS ✓

UNDECIPHERABLE GRAY SCALE DOCUMENTS

IMAGES ARE THE BEST AVAILABLE COPY. AS RESCANNING WILL NOT CORRECT IMAGES, PLEASE DO NOT REPORT THE IMAGES TO THE PROBLEM IMAGE BOX.

TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-You SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 1 (PRIOR ART)




FIG. 2 (PRIOR ART)




FIG. 3A (PRIOR ART)




FIG. 3B (PRIOR ART)




FIG. 3C (PRIOR ART)






FIG. 4A (PRIOR ART)



TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-Youn SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 4B (PRIOR ART)



TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-Youn SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 5A (PRIOR ART)




FIG. 5B (PRIOR ART)






FIG. 6



TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-Youn SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 7



TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-Youn SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 8A




FIG. 8B




FIG. 9A




FIG. 9B






FIG. 10




TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-Youn SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 11



TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-Youn SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 12A



TITLE: OPTICAL PICKUP ACTUATOR FOR REDUCING VIBRATION
INVENTORS: Byung-Youn SONG et al.
SERIAL NO.: TO BE ASSIGNED
DOCKET NO.: 1793.1085

FIG. 12B




FIG. 12C

